



**Technical Bulletin 07
E-max™ Ball Chamber
Anti Static Properties**

Date Issued: 2/10/2005

**Product Effected: E-max Bingo Console Ball Chamber Arrow Part
Number: HH601 (all revisions)**

Problem: Static build up in the ball chamber causes poor ball action

The Emax ball console achieves a static free environment through a combination of the anti-static mat, the anti-static ring and the anti-static coating on the E-max Bingo Balls.

The anti-static coating on the ball is vital to the proper operation of the E-max ball chamber. Many reports of excess static and poor ball action related to the E-max ball chamber are directly related to the ball type being used in the console.

Arrow International recommends using *only* Atlas balls in the Emax console.